

APPENDIX F
PHOTOGRAPHIC LOG



ENHANCED RIPARIAN AREA STREAM CHANNEL ASSESSMENT Direction: North	DESCRIPTION	Bank Type 1	1
	LOCATION	Site 1: Allen Creek	Date August 6, 2007
	PHOTOGRAPHER	Brock Emmert	



ENHANCED RIPARIAN AREA STREAM CHANNEL ASSESSMENT Direction: Northeast	DESCRIPTION	Bank Type 2 and gulley	2
	LOCATION	Site 1: Allen Creek	Date August 6, 2007
	PHOTOGRAPHER	Brock Emmert	



ENHANCED RIPARIAN AREA STREAM CHANNEL ASSESSMENT Direction: Southwest	DESCRIPTION	Gulley headcutting in pasture	3
	LOCATION	Site 2: Allen Creek	Date August 6, 2007
	PHOTOGRAPHER	Brock Emmert	



ENHANCED RIPARIAN AREA STREAM CHANNEL ASSESSMENT Direction: North	DESCRIPTION	Bank Type 1	4
	LOCATION	Site 2: Allen Creek	Date August 7, 2007
	PHOTOGRAPHER	Brock Emmert	



ENHANCED RIPARIAN AREA STREAM CHANNEL ASSESSMENT Direction: East	DESCRIPTION	Bank Type 2	5
	LOCATION	Site 1: Allen Creek	Date August 7, 2007
	PHOTOGRAPHER	Brock Emmert	



ENHANCED RIPARIAN AREA STREAM CHANNEL ASSESSMENT Direction: North	DESCRIPTION	Bank Type 1	6
	LOCATION	Site 3: Cottonwood River	Date August 8, 2007
	PHOTOGRAPHER	Brock Emmert	



ENHANCED RIPARIAN AREA STREAM CHANNEL ASSESSMENT Direction: East	DESCRIPTION	Bank Type 2	7
	LOCATION	Site 3: Cottonwood River	Date August 8, 2007
	PHOTOGRAPHER	Brock Emmert	



ENHANCED RIPARIAN AREA STREAM CHANNEL ASSESSMENT Direction: South	DESCRIPTION	Gully Headcut	8
	LOCATION	Site 3: Cottonwood River	Date August 9, 2007
	PHOTOGRAPHER	Brock Emmert	



ENHANCED RIPARIAN AREA STREAM CHANNEL ASSESSMENT Direction: East	DESCRIPTION	Bank Type 3	9
	LOCATION	Site 3: Cottonwood River	Date
	PHOTOGRAPHER	Brock Emmert	August 9, 2007



ENHANCED RIPARIAN AREA STREAM CHANNEL ASSESSMENT Direction: Southeast	DESCRIPTION	Bank Type 4	10
	LOCATION	Site 3: Cottonwood River	Date
	PHOTOGRAPHER	Brock Emmert	August 9, 2007



ENHANCED RIPARIAN AREA STREAM CHANNEL ASSESSMENT Direction: North	DESCRIPTION	Bank Type 1	11
	LOCATION	Site 4: Allen Creek	Date
	PHOTOGRAPHER	Brock Emmert	August 10, 2007



ENHANCED RIPARIAN AREA STREAM CHANNEL ASSESSMENT Direction: South	DESCRIPTION	Bank Type 2	12
	LOCATION	Site 4: Allen Creek	Date
	PHOTOGRAPHER	Brock Emmert	August 10, 2007



ENHANCED RIPARIAN AREA STREAM CHANNEL ASSESSMENT Direction: Southeast	DESCRIPTION	Bank Type 1 with concrete rubble	13
	LOCATION	Site 5: Dow Creek	Date August 13, 2007
	PHOTOGRAPHER	Brock Emmert	



ENHANCED RIPARIAN AREA STREAM CHANNEL ASSESSMENT Direction: South	DESCRIPTION	Bank Type 1	14
	LOCATION	Site 6: Dow Creek	Date August 14, 2007
	PHOTOGRAPHER	Brock Emmert	



ENHANCED RIPARIAN AREA STREAM CHANNEL ASSESSMENT Direction: East	DESCRIPTION	Bank Type 2	15
	LOCATION	Site 6: Dow Creek	Date
	PHOTOGRAPHER	Brock Emmert	August 14, 2007



ENHANCED RIPARIAN AREA STREAM CHANNEL ASSESSMENT Direction: Northwest	DESCRIPTION	Log Jam	16
	LOCATION	Site 6: Dow Creek	Date
	PHOTOGRAPHER	Brock Emmert	August 14, 2007



ENHANCED RIPARIAN AREA STREAM CHANNEL ASSESSMENT Direction: South	DESCRIPTION	Bank Type 3	17
	LOCATION	Site 6: Dow Creek	Date
	PHOTOGRAPHER	Brock Emmert	August 14, 2007



ENHANCED RIPARIAN AREA STREAM CHANNEL ASSESSMENT Direction: West	DESCRIPTION	Bank Type 1	18
	LOCATION	Site 7: Neosho River	Date
	PHOTOGRAPHER	Brock Emmert	August 15, 2007



ENHANCED RIPARIAN AREA STREAM CHANNEL ASSESSMENT Direction: Northeast	DESCRIPTION	Bank Type 2	19
	LOCATION	Site 7: Neosho River	Date
	PHOTOGRAPHER	Brock Emmert	August 15, 2007



ENHANCED RIPARIAN AREA STREAM CHANNEL ASSESSMENT Direction: East	DESCRIPTION	Bank Type 3	20
	LOCATION	Site 7: Neosho River	Date
	PHOTOGRAPHER	Brock Emmert	August 15, 2007



ENHANCED RIPARIAN AREA STREAM CHANNEL ASSESSMENT Direction: East	DESCRIPTION	Bank Type 1	21
	LOCATION	Site 8: Cottonwood River	Date
	PHOTOGRAPHER	Brock Emmert	August 16, 2007



ENHANCED RIPARIAN AREA STREAM CHANNEL ASSESSMENT Direction: Northeast	DESCRIPTION	Bank Type 2	22
	LOCATION	Site 8: Cottonwood River	Date
	PHOTOGRAPHER	Brock Emmert	August 16, 2007




ENHANCED RIPARIAN AREA STREAM CHANNEL ASSESSMENT Direction: Southwest	DESCRIPTION	Bank Type 3	23
	LOCATION	Site 8: Cottonwood River	Date
	PHOTOGRAPHER	Brock Emmert	August 17, 2007



ENHANCED RIPARIAN AREA STREAM CHANNEL ASSESSMENT Direction: North	DESCRIPTION	Bank Type 1	24
	LOCATION	Site 9: Neosho River	Date
	PHOTOGRAPHER	Brock Emmert	Sept. 17, 2007



ENHANCED RIPARIAN AREA STREAM CHANNEL ASSESSMENT Direction: East	DESCRIPTION	Concrete rubble on right bank	25
	LOCATION	Site 9: Neosho River	Date Sept. 17, 2007
	PHOTOGRAPHER	Brock Emmert	



ENHANCED RIPARIAN AREA STREAM CHANNEL ASSESSMENT Direction: North	DESCRIPTION	Bank Type 2	26
	LOCATION	Site 9: Neosho River	Date Sept. 17, 2007
	PHOTOGRAPHER	Brock Emmert	



ENHANCED RIPARIAN AREA STREAM CHANNEL ASSESSMENT Direction: South	DESCRIPTION	Overgrazed pasture	27
	LOCATION	Plumb Creek	Date Sept. 18, 2007
	PHOTOGRAPHER	Brock Emmert	



ENHANCED RIPARIAN AREA STREAM CHANNEL ASSESSMENT Direction: East	DESCRIPTION	Bank Type 1	28
	LOCATION	Site 10: Plumb Creek	Date Sept. 18, 2007
	PHOTOGRAPHER	Brock Emmert	



ENHANCED RIPARIAN AREA STREAM CHANNEL ASSESSMENT Direction: East	DESCRIPTION	Bank Type 2	29
	LOCATION	Site 10: Plumb Creek	Date
	PHOTOGRAPHER	Brock Emmert	Sept. 18, 2007



ENHANCED RIPARIAN AREA STREAM CHANNEL ASSESSMENT Direction: Southwest	DESCRIPTION	Bank Type 3	30
	LOCATION	Site 10: Plumb Creek	Date
	PHOTOGRAPHER	Brock Emmert	Sept. 18, 2007